

## SAFETY SHARE

### **HYDRAULIC SAFETY**



# AGENDA

#### Introduction to FLSmidth Cement Grinding Technology

Overview of Key Technologies: OK<sup>™</sup> mill.

Energy Efficiency and Power Consumption

FLSmidth Cement Services

Case Studies and Practical Applications

Q&A Session



## FLSMDTH GRNDING SOLUTIONS

#### **FLSMIDTH GRINDING PRODUCTS OVERVIEW** RAW CEMENT HRP **OK Raw Mill** ATOX **OK Cement Mill Ball Mill HRP** Raw HRP pre-grinding Coal Mill Ball mill grinding STAND ALONE STAND ALONE COMBINED

### **IMPORTANCE OF EFFICIENT GRINDING SOLUTIONS**

#### TYPICAL POWER DISTRIBUTION IN CEMENT PLANT



Grinding section	Fineness	kWh/t of Clinker
Raw Meal	12-15% on 90 μm	10 - 25
Raw Coal	12-15% on 90 μm	2 - 4
Cement	3000-6000 cm2/gm 1-8% on 45 μm	25 - 60
Total		45 - 90

■ Crushing ■ Grinding ■ Pyro ■ Packing





## FLEXIBLE OPERATION

### ok™ MILL FLEXIBILITY





# OKM MILL

Condition	Production t/h	Blaine cm²/g	kWh/t Mill	kWh/t fan	kWh/t sep.	Total kWh/t
2 rollers	92	3600	15.2	13.6	0.7	29.4
4 rollers	144	3800	16.1	8.7	0.6	25.4
Guaranteed	140	-	17.2	-	0.6	_

### OKM MILL **PRODUCT FLEXIBILITY**



### OK<sup>M</sup> MILL **PRODUCTS**





#### MILL COMPARISON FOR CEMENT GRINDING SPECIFIC POWER CONSUMPTION



#### OK™ MILL VS. BALL MILLS ENERGY CONSUMPTION

	OK™ mill	Ball mill	RP + Ball mill
Blaine cm <sup>2</sup> /g		3800	
Total kWh/t	29	40.8	37.4
% increase in kWh/t		~ 40%	~ 29%

## SEPARATOR AND POWER SAVING

### **ROKSH AND RARM SEPARATOR**



### **ROKSH SEPARATOR FOR OK CEMENT MILLS**



- Physical dimensions optimized to enhance velocity profile
- lower air velocity
- Less wear
- Lower differential pressure
- Lower separator power

THE ROKSH SEPARATOR FOR CEMENT GRINDING IN VERTICAL ROLLER MILL

### ROKSH® RARM® SEPARATOR UPGRADE



### EASE OF INSTALLATION FROM OLD SEPARATOR TO ROKSH



**BEFORE** 



AFTER

## FLSmidth Cement Services

## Poll Question 3 What do you believe is more valuable to you?

One time per year on-site mechanical service

- One time per year a comprehensive process audit
  - Having an Online Conditioning monitoring service agreement

## Grinding System AUDIT





### **IMPROVE YOUR RESULTS WITH OUR AUDITS**



### **VERTICAL ROLLER MILL AUDIT**



# CONDITION ONITORING **SERVICES**

#### ENABLING YOU TO ACT BEFORE IT'S TOO LATE DETECT POTENTIAL FAILURES TO AVOID ACTUAL FAILURES



### **INSTRUMENTATION AND SENSORS**



Stop Impact and Force

### ONLINE CONDITION MONITORING SERVICES FOCUSED ANALYTICS

MILL AIR CIRCUIT & FAN	GRINDING HYDRAULIC SYSTEM	MILL GEAR UNIT	SEPARATOR RELIABILITY
<ul> <li>Indicators         <ul> <li>of increase in             circuit false air</li> </ul> </li> </ul>	<ul> <li>Frequency of pump activation</li> <li>Holding pressure settings</li> </ul>	<ul> <li>Input Torque in VRM gear.</li> <li>Table wobbling and tilting in VRM gear</li> </ul>	<ul> <li>Monitoring of Separator behavior, to indicate replacement time.</li> </ul>
	<ul> <li>Indicators of leaks and mis-operation</li> </ul>	<ul> <li>High resolution gear and bearing vibration.</li> </ul>	

## ROLLER REBUILD SERVICE

### RESTORE YOUR ROLLERS TO THE ORIGINAL DESIGN CONDITION





## HOW IT WORKS

- Roller rebuilds can return your rollers to design condition, for both ATOX<sup>®</sup> and OK<sup>™</sup> Mills
- A comprehensive inspection is done to the roller Identifies what needed to bring it back to OEM conditions
- Our workshops carry out the necessary work to rebuild the roller

















### **NORMAL WEAR**









## **VERTICAL MILL WEAR**





### WEAR/DAMAGE FROM UN-OPTIMIZED OPERATION



### **WEAR/DAMAGE FROM UN-OPTIMIZED OPERATION**

#### 1 Executive Summary

- This report shows the effect of changing Mill operating parameters (grinding pressure & layer thickness) which done by FLS specialist during his visit 13-15 October 2014 on the wear rate of both rollers & table wear segments.
- According to wear rate measurements it was observed that from 13-August-2014 to 30-September-2014 the mill produced 35,929 ton with total wear rate 20.4 g/t, and from 30-September-2014 to 11-November-2014 the mill produced 38,412 ton with total wear rate 11.8 g/t.
- After decreasing of grinding pressure & increasing of layer thickness the total wear rate decreased from 20.4 g/t to 11.8 g/t (decreased about 58%).
- After adjusting of mill parameters the phenomena of broken edges for both rollers & table wear segments was disappeared

### THE MAJOR CHALLENGE WITH SEPARATORS IN OPERATION IS WEAR! OPERATION CHALLENGES OF SEPARATORS



### **OPERATION CHALLENGES OF SEPARATORS**

Lar dire

Large particles are rejected by the rotor blades and directed onto the guide vanes

Severely worn rotor blades will reject fewer parts

Severely worn guide vanes will let rejected particles pass to outside for repeated processing

#### THE RESULT OF DETERIORATED ROTOR AND GUIDE VANES IS..

#### A less efficiently working separator

- Decreased sharpness of separation Flatter product curve
- More bypass of fine material to mill Instability and vibrations of mill







### ALREADY LUMPS AND BUILD-UPS IN SILO?

If these pictures are already a reality, there is nothing that can be done operationally to remove it.

By following the guidelines, further development of lumps and build-ups can of course be prevented.







### **VRM OPERATION STRATEGIES**



#### MILL OUTLET TEMP. ~75DEG.C.

- Low dehydration level
  - Compromise the positive effect of high dehydration level
- Minimum operation of HGG
- Challenge to obtain a low outlet temperature with hot clinker (increasing water injection)

#### STORAGE IN SILO @ LOW TEMPERATURE

Below 70deg.C., no further gypsum dehydration in silo

#### MILL OUTLET TEMP. ~120DEG.C.

- High dehydration level
  - Positive influence on strength development
  - Positive effect on gypsum activity

#### STORAGE IN SILO @ HIGH TEMPERATURE

If gypsum is not dehydrated in the mill, it will continue to dehydrate in the silo (= potential for silo build-ups)



## HOW OCMS SAVED A VRM FROM FAILURE?

Occordente (Contraction)
 Occordente

## CUSTOMER STORY HYDRAULIC SYSTEM

#### **OBSERVATION**

Hydraulic leak suspected due to "irregular hydraulic pump cycle length"

#### **ROOT CAUSE ANALYSIS**

Internal leakage from cylinder

#### RECOMMENDATION

- Following up pump start-stop intervals.
- Air vent for hydraulic circuit.
- Spare seal kit to be available.

#### SAVINGS OF \$45 K, AVOID NEW

- Pump
- Cylinder rod
- Seal kit

« Glad that the CMS team detected the failure in the hydraulic seal and replaced from cylinder#2 as it was damaged ,and CMS allowed the plant team to order the spares on-time without impact on Mill operation »

#### PLANT MANAGER

Cement customer in Poland





## customer story **SEPARATOR**

#### EVENT

- Separator bottom & middle bearings high temperature High Mill outlet temp
- Repeated High alarm of mill outlet gases temperature during mill operation tends to 125°C.

#### RECOMMENDATION

- Check the automatic grease cycle/consumption function and the amount of grease in the tank.
- Control the mill outlet gases

#### VALUE

- Up to 500K\$ to replace separator bearings and possible shaft repair.
- Time to prepare the needed spares in advance.



#### CUSTOMER STORY OPTIMIZATION



#### EVENT

• The mill runs with low-low grinding rollers bed layer thickness for most of the mill operation, which is directly correlated with insufficient water injection flow rate.

#### RECOMMENDATION

- To increase the bed layer thickness, gradually increase the water spray flow rate up to 2 % of the mill fresh feed rate.
- To stabilize mill ΔP and bed thickness layers adapt the following operating parameters:
  - Mill feed rate
  - Water flow
  - Grinding pressure
  - Mill fan draft
  - Separator speed

#### VALUE

- Increase mill productivity by 50 tph.
- Avoid mill vibration.



Ahmed Seaf

Ahmed.seaf@flsmidth.com

1110 American Parkway, Allentown, PA 18109 • USA • www.flsmidth-cement.com

# FLSMDTH CEMENT



